

In the Specification:

Please amend the paragraph at page 2, lines 9 to 11, as follows:

In the case of the baby carriage 1 shown in Fig 1, since there ~~[[is]]~~ are gaps above both sides of the seat surface portion 6 of the seat hammock, that is, under the handrails 4, a child seated in the seat could put a hand in the gap.

Please amend the paragraph at page 7, lines 13 to 17, as follows:

As can be clear from Figs. 6 and 7, the upper side surface portion 32a of the seat hammock 30 is wrapped around the upward extension frame member 41 of the baby carriage to be fixed thereto. The set button 34 of the upper side surface portion 32a engages with a receive receiver clip fixed to the upward extension frame member 41.

Please amend the paragraph at page 7, lines 18 to 22, as follows:

Furthermore, the upper connection end 33c of the lower side surface portion 33 of the seat hammock 30 is also wrapped around the upward extension frame member 41 to be fixed thereto. The set button 35 of the ~~lower side surface portion~~ upper connection end 33c engages with a receive receiver clip fixed to the upward extension frame member 41.

[RESPONSE CONTINUES ON NEXT PAGE]

4628/WFF:ar

- 2 -